

Ersatzteilliste 2823

Spare parts list

Liste de pièces de rechange

Blatt/Page 1 von/of/de 8
26.01.2017




Olsberg GmbH

Hüttenstraße 38, 59939 Olsberg
T +49 2962 805-0, F +49 2962 805-180
info@olsberg.com, olsberg.com

Corvus

- 28/8861 Stahl schwarz / Steel black / Acier noir
- 28/8863 Naturstein serpentin / Natural stone serpentin / Pierre naturelle serpentin
- 28/8864 Keramik vanilla / Ceramic vanilla / Céramique vanilla

**dargestellte
Verkleidung/
pictured cladding/
habillage imagé:**
28/8861








Ersatzteilliste 2823
Spare parts list
Liste de pièces de rechange

Blatt/Page 2 von/of/de 8
26.01.2017

Olsberg GmbH
Hüttenstraße 38, 59939 Olsberg
T +49 2962 805-0, F +49 2962 805-180
info@olsberg.com, olsberg.com

Corvus

- 28/8861 Stahl schwarz / Steel black / Acier noir
- 28/8863 Naturstein serpentin / Natural stone serpentin / Pierre naturelle serpentin
- 28/8864 Keramik vanilla / Ceramic vanilla / Céramique vanilla





Ersatzteilliste 2823
Spare parts list
Liste de pièces de rechange

Blatt/Page 3 von/of/de 8
26.01.2017

Corvus

- 28/8861 Stahl schwarz / Steel black / Acier noir
- 28/8863 Naturstein serpentin / Natural stone serpentin / Pierre naturelle serpentin
- 28/8864 Keramik vanilla / Ceramic vanilla / Céramique vanilla




Ersatzteilliste 2823
Spare parts list
Liste de pièces de rechange

Blatt/Page 4 von/of/de 8
26.01.2017

Corvus

- 28/8861 Stahl schwarz / Steel black / Acier noir
- 28/8863 Naturstein serpentin / Natural stone serpentin / Pierre naturelle serpentin
- 28/8864 Keramik vanilla / Ceramic vanilla / Céramique vanilla

**dargestellte
Verkleidung/
pictured cladding/
habillage imagé:**
28/8861



Ersatzteilliste 2823
Spare parts list
Liste de pièces de rechange


Blatt/Page 5 von/of/de 8
26.01.2017



Olsberg GmbH
Hüttenstraße 38, 59939 Olsberg
T +49 2962 805-0, F +49 2962 805-180
info@olsberg.com, olsberg.com

Corvus

- 28/8861 Stahl schwarz / Steel black / Acier noir
- 28/8863 Naturstein serpentin / Natural stone serpentin / Pierre naturelle serpentin
- 28/8864 Keramik vanilla / Ceramic vanilla / Céramique vanilla




Ersatzteilliste 2823
Spare parts list
Liste de pièces de rechange

Blatt/Page 6 von/of/de 8
26.01.2017

Olsberg GmbH
Hüttenstraße 38, 59939 Olsberg
T +49 2962 805-0, F +49 2962 805-180
info@olsberg.com, olsberg.com

Corvus

- 28/8861 Stahl schwarz / Steel black / Acier noir
- 28/8863 Naturstein serpentin / Natural stone serpentin / Pierre naturelle serpentin
- 28/8864 Keramik vanilla / Ceramic vanilla / Céramique vanilla




Ersatzteilliste 2823
Spare parts list
Liste de pièces de rechange

Blatt/Page 7 von/of/de 8
26.01.2017

Corvus

- 28/8861 Stahl schwarz / Steel black / Acier noir
- 28/8863 Naturstein serpentin / Natural stone serpentin / Pierre naturelle serpentin
- 28/8864 Keramik vanilla / Ceramic vanilla / Céramique vanilla



**dargestellte Verkleidung/
pictured cladding/
habillage imagé:**
28/8863


Ersatzteilliste 2823
Spare parts list
Liste de pièces de rechange

Blatt/Page 8 von/of/de 8
26.01.2017

Olsberg GmbH
Hüttenstraße 38, 59939 Olsberg
T +49 2962 805-0, F +49 2962 805-180
info@olsberg.com, olsberg.com

Corvus

- 28/8861 Stahl schwarz / Steel black / Acier noir
- 28/8863 Naturstein serpentin / Natural stone serpentin / Pierre naturelle serpentin
- 28/8864 Keramik vanilla / Ceramic vanilla / Céramique vanilla



**dargestellte Verkleidung/
pictured cladding/
habillage imagé:**
28/8864